



into the ground up to 44' deep.

The tank bottom, initially installed by another contractor, has failed twice since

Leakage and Corrosion

